

Windows 2000 Drivers
Fiery ZX 6/9 v1.1

Problem:

Unable to print to the Fiery ZX6/9 Print Server on the Windows 2000 operating system with currently supplied drivers.

Solution:

Install the printer using the included driver files listed below.

These drivers are considered final release. This means that these drivers have been released as is. Validation was performed and all issues found are listed below. Further testing will not be conducted nor supported.

This update consists of the following (4) files for each language:

File Name	File Size
Efax3010.ppd	68 KB
Efax5010.ppd	92 KB
Efax7010.ppd	68 KB
Oemsetup.inf	4 KB

Installation Instructions:

1. Go to **Start/Settings/Printers** and double-click on **Add Printer**
2. Follow the On-screen instructions

Note: When installing the printer driver, you will be asked for additional files. These files will be found on the Windows 2000 CD.

Known Issues:

1. Job Notes are not supported.
2. Custom Paper sizes are not supported

Fiery Utilities are not supported on the Windows 2000 operating system.